







REV.





	AMS CONSTRUCTIONS PTY LTD ABN: 95 607 514 330 DO NOT SCALE FROM THESE DRAWINGS. VERIFY ALL DIMENSIONS ON SITE BEFORE COMMENCING CONSTRUCTION OR SHOP DRAWINGS. THIS DRAWING IS COPYRIGHT NO PART MAY BE REPRODUCED OR OTHERWISE PAILT WITH WITHOUT THE	PROJECT/	drawing/ EXISTING ELEVATIONS	SCALE ON A3/ 1 : 150		DATE/ 14.09.2022
		ROCKHAMPTON MIXED USE 113 EAST STREET, ROCKHAMPTON OLD 4700		DRAWN MA	CHECKED AP	PROJ NO/ AMC 06.21-22/04
		TIS LAST STILLT, NOCKTAMPTON QED 4700		TOWN		DRAWING NO/ REV.
6 ALBERT ST, PRESTON, VIC, 3072 P: 03 9462 9111	PERMISSION OF THE RELEVANT ARCHITECT OR BUILDING DESIGNER			PLA	NNING	TP06



Reference: 2103-28It01 Date: 06/09/2022

Chemist Warehouse ATT: Mitchell Ashby Via Email: <u>mitchell.ashby@amscon.com.au</u>

ROCKHAMPTON REGIONAL COUNCIL

APPROVED PLANS

These plans are approved subject to the current conditions of approval associated with

Development Permit No.: D/133-2022 Dated: 31 January 2023

To Whom It May Concern:

Re: Dilapidated Building – Chemist Warehouse No. 113 East Street, Rockhampton.

A representative of our office completed a visual condition assessment inspection of the above building on Friday 16 April 2021. The key findings of this inspection are included within the structural report Reference No. 2103-28rp01 28/04/2021, prepared by this office.

In summary, the existing building was in an extremely dilapidated state. Notable building damage included:

- Severe foundation subsidence resulting in crack widths of approximately 50mm to the external masonry walls.
- Structurally unsound cantilevered steel awnings to the building facade, spanning over public pedestrian foot traffic.
- Deviation of up to 100mm within the first-floor frame structure.
- Water ingress to the upper roof structure.
- Severe sagging of plaster ceiling linings considered to be high-risk of collapse.

To stabilise the existing foundations to an acceptable level, deep piling / underpinning of the existing footings founding through the underlying river /marine clays and into bedrock would be necessary, requiring large machinery for installation. Due to the existing adjoining building to the North, and the new development to the southern boundary, suitable access for such machinery is not available, and foundation stabilisation through means of deep piling is not feasible.

From our review, it is the opinion of this office that the building is structurally unsound and is incapable of reasonably being made structurally sound in terms of the financial cost of the required works.

Should you require further information, please contact the undersigned.

Yours faithfully,

Scott Fairley B.Eng. (Civil), RPEQ 8423, BLA Registration No. PE0003890